

APPLIED MARINE ENGINEERING

Attempt ALL questions

Marks for each part question are shown in brackets

1. (a) List FIVE different desirable properties of aluminium. (5)
- (b) In modern vessels identify parts that utilises EACH of the properties listed in part (a). (5)

2. With reference to EACH of the following materials, list their percentage composition and a different application for EACH material on board, stating, with reasons, why they are suitable for this application:
 - (a) cupro-nickel; (2)
 - (b) aluminium bronze; (2)
 - (c) admiralty brass; (2)
 - (d) duralumin; (2)
 - (e) solder. (2)

3. With reference to case hardening steel components:
 - (a) describe the changes that occur with this process; (3)
 - (b) explain why it may be required; (2)
 - (c) describe EACH of the following processes:
 - (i) a simple shipboard process; (3)
 - (ii) solid pack carburising. (2)

4. With reference to fatigue failure of components:
 - (a) describe how material fatigue testing is carried out in the laboratory; (2)
 - (b) sketch the surface appearance of a fatigue fracture; (2)
 - (c) describe the THREE stages of the failure; (3)
 - (d) list the methods available on board to limit the possibility of fatigue failure to a propeller shaft. (3)

5. Describe, with the aid of sketches, FIVE defects that may be present on a weld produced using the covered electrode welding process. (10)

*porosity
slag
undercut
underfill
incomplete fusion*

*alignment
rubber coupling*

6. With reference to the cathodic protection of hull fittings:
- (a) explain how sacrificial anodes achieve this; (2)
 - (b) state where sacrificial anodes would be fitted and why; (4)
 - (c) describe an impressed current system, stating the principle on which it works. (4)
7. Explain EACH of the following terms:
- (a) galvanic corrosion; (2)
 - (b) cavitation damage; (2)
 - (c) erosion damage; (2)
 - (d) stress corrosion; (2)
 - (e) atmospheric corrosion. (2)
8. (a) Describe with the aid of a sketch, how Bi-metallic strips are utilised to measure temperature. (8)
- (b) State a typical application for this type of device and its main shortcoming. (2)
9. With reference to engine governors, explain EACH of the following terms:
- (a) sensitivity; (2)
 - (b) hunting; (2)
 - (c) speed droop; (2)
 - (d) stability; (2)
 - (e) isochronous governing. (2)

10. (a) State the reasons for fitting a pneumatic process valve with EACH of the following:
- (i) a volume booster; (2)
 - (ii) a feedback positioner. (2)
- (b) State, with reasons, the type of actuator fitted to the process valves for EACH of the following systems:
- (i) a fuel supply system in which the valve must not move on loss of power to the control system; *fail set* (3)
 - (ii) a lubrication oil cooling system in which the valve diverts the oil through a cooler. *fail safe.* (3)

1. (a) List FIVE different desirable properties of aluminium. (5)
- (b) In modern vessels identify parts that utilises EACH of the properties listed in part (a). (5)


(a) Five desirable properties of aluminium (5 marks)

1. **Low density / lightweight** – about one-third the density of steel.
2. **Good corrosion resistance** – natural oxide film resists seawater attack.
3. **High thermal and electrical conductivity.**
4. **Good formability and machinability** – easy to fabricate and shape.
5. **Attractive appearance** – can be polished, anodised, or painted; also non-toxic.

(Other acceptable answers: non-magnetic, high strength-to-weight ratio when alloyed, recyclable.)

(b) Applications of each property on modern vessels (5 marks)

1. **Lightweight** → Superstructure, decks, bulkheads: reduces top-weight, improves stability, increases payload.
2. **Corrosion resistance** → Hull plating, masts, deck fittings exposed to seawater.
3. **High conductivity** → Electrical busbars, cabling, heat exchangers, refrigeration piping.
4. **Good formability/machinability** → Complex fittings, accommodation furniture, ladders, and hatches.
5. **Appearance / non-toxic** → Galley equipment, handrails, decorative trims, interior panels.



(a) Cupro-nickel (2)

- **Composition:** ~70–90% copper, 10–30% nickel (often 70/30 or 90/10).
- **Application:** Seawater piping, condensers, and heat exchangers.
- **Reason:** Excellent **corrosion resistance in seawater**, good thermal conductivity, resistant to biofouling.

(b) Aluminium bronze (2)

- **Composition:** ~88–90% copper, 8–11% aluminium, small % of iron/nickel.
- **Application:** Propellers and pump components.
- **Reason:** High **strength and toughness**, very good **corrosion resistance** in seawater, resistant to cavitation/erosion.

(c) Admiralty brass (2)

- **Composition:** ~70% copper, 29% zinc, ~1% tin.
- **Application:** Condenser and heat exchanger tubes.
- **Reason:** Tin improves resistance to **dezincification**, good thermal conductivity, resists seawater corrosion.

(d) Duralumin (2)

- **Composition:** ~90–95% aluminium, 4% copper, small amounts of magnesium, manganese.
- **Application:** Deckhouse structures, ladders, masts.
- **Reason:** Lightweight, strong, good machinability – ideal for **reducing topside weight**.

(e) Solder (2)

- **Composition:** Traditionally ~60% tin, 40% lead (now lead-free types: Sn-Cu or Sn-Ag-Cu).
- **Application:** Electrical wiring and electronic joints.
- **Reason:** Low melting point, good wettability, provides strong **electrical and mechanical bond**.

3. With reference to case hardening steel components:

- | | |
|--|-----|
| (a) describe the changes that occur with this process; | (3) |
| (b) explain why it may be required; | (2) |
| (c) describe EACH of the following processes: | |
| (i) a simple shipboard process; | (3) |
| (ii) solid pack carburising. | (2) |
- porosity
slag
undercut
underfill
incomplete fusion*

(a) Describe the changes that occur with this process (3 marks)

- The **surface layer of the steel is hardened** by adding carbon/nitrogen and then quenching, producing **hard martensite** at the surface.

- The **core remains softer and tougher**, usually ferrite/pearlite, retaining ductility and impact resistance.
- The result is a component with a **hard, wear-resistant surface** and a **tough, shock-resistant core**.

(b) Why it may be required (2 marks)

- To resist **surface wear, abrasion, and fatigue** in service (e.g., gears, cams, shafts).
- While maintaining a **tough, ductile core** to absorb shocks and prevent brittle fracture.

(c) Case hardening processes

(i) A simple shipboard process (3 marks)

- **Flame hardening**: Heat the steel surface locally using an oxy-acetylene flame, then rapidly quench with water/air spray.
- Produces a thin **hardened surface layer** (martensite), leaving the core unaffected.
- Advantage: Simple, portable, quick for local repairs onboard.

(Alternative acceptable: induction hardening – using a high-frequency coil, then quenching.)

(ii) Solid pack carburising (2 marks)

- Components are packed in a sealed box with a **carbonaceous material** (e.g., charcoal plus barium carbonate as an energiser).
- Heated to around **900 °C** for several hours.
- Carbon diffuses into the steel surface, enriching it. On quenching, the **case becomes hard** while the core stays tough.

4. With reference to fatigue failure of components:

- describe how material fatigue testing is carried out in the laboratory; (2)
- sketch the surface appearance of a fatigue fracture; (2)
- describe the **THREE** stages of the failure; (3)
- list the methods available on board to limit the possibility of fatigue failure to a propeller shaft. (3)

*alignment
rubber coupling*

(a) How material fatigue testing is carried out in the laboratory (2 marks)

- A specimen is subjected to **cyclic loading** (e.g., rotating bending, axial loading, or torsion) at a known stress level.

- The **number of cycles to failure** is recorded, producing an **S–N curve** (stress vs. number of cycles) which shows fatigue life.
-

(b) Sketch/surface appearance of a fatigue fracture (2 marks)

(Describe if no sketch possible)

- Surface shows **beach marks or concentric rings** from progressive crack growth.
 - A relatively **smooth area** where the crack propagated slowly, ending in a **rough, crystalline final fracture zone** where sudden failure occurred.
-

(c) The three stages of fatigue failure (3 marks)

1. **Crack initiation** – starts at stress concentrations (surface scratches, keyways, weld defects).
 2. **Progressive crack growth** – under repeated cyclic stresses, crack slowly extends; beach marks visible.
 3. **Final sudden fracture** – remaining section fails catastrophically once it can no longer sustain the load.
-

(d) Methods onboard to limit fatigue failure of a propeller shaft (3 marks)

- Ensure **accurate alignment** of shafting and couplings.
 - Fit **flexible/rubber couplings** to absorb shocks and misalignment.
 - Maintain correct **bearing lubrication and support** to reduce cyclic stresses.
 - Avoid sharp corners/keyway stress raisers; keep good surface finish.
 - Regular inspections for **cracks or corrosion pitting**.
-

5. Describe, with the aid of sketches, FIVE defects that may be present on a weld produced using the covered electrode welding process.

(10)

Q5. Describe, with the aid of sketches, FIVE defects that may be present on a weld produced using the covered electrode welding process. (10 marks)

1. Porosity

- Small gas holes trapped in the solidified weld metal.
- Caused by **contaminants, damp electrodes, or insufficient shielding**.
- Weakens weld by reducing cross-sectional area.

2. Slag Inclusions

- Non-metallic particles (flux/slag) trapped in the weld.
 - Caused by **poor cleaning between passes** or incorrect electrode angle.
 - Reduces strength and can initiate cracks.
-

3. Lack of Fusion (Incomplete Fusion)

- Weld metal fails to fuse properly with the parent metal or previous bead.
 - Caused by **low heat input, incorrect electrode angle, or poor technique**.
 - Creates planes of weakness along the joint.
-

4. Undercut

- Groove melted into the parent metal at the toe of the weld that is not filled with weld metal.
 - Caused by **excessive current or incorrect travel speed**.
 - Acts as a **stress concentration point**, reducing fatigue strength.
-

5. Cracking

- Can be **hot cracks** (during solidification) or **cold cracks** (after cooling).
 - Causes include **high restraint, hydrogen embrittlement, poor design, or rapid cooling**.
 - Severely compromises weld integrity.
-

Answering with sketches

- Each of the above should ideally be accompanied by a **simple labelled sketch** (e.g., weld bead cross-section showing porosity holes, slag inclusion lines, lack of fusion gap, undercut groove, and a crack line).

6. With reference to the cathodic protection of hull fittings:
- (a) explain how sacrificial anodes achieve this; (2)
 - (b) state where sacrificial anodes would be fitted and why; (4)
 - (c) describe an impressed current system, stating the principle on which it works. (4)

(a) How sacrificial anodes achieve cathodic protection (2 marks)

- Sacrificial anodes are made from a **more reactive (anodic) metal** such as zinc, aluminium, or magnesium.
- When connected to the steel hull, the anode preferentially **corrodes (sacrifices itself)**, supplying electrons to the hull and making the hull a **cathode** → preventing its corrosion.

(b) Where sacrificial anodes are fitted and why (4 marks)

- **Locations:**
 - Along the ship's **hull**, especially near the stern.
 - Around **sea chests** and **bilge keels**.
 - On or near **rudders, shafts, propellers, and stern gear**.
- **Reasons:**
 - These areas are most exposed to seawater and prone to galvanic corrosion.
 - Ensures **uniform protection** of vulnerable fittings and areas of turbulent flow.

(c) Impressed current system: principle and description (4 marks)

- Uses **inert anodes** (e.g., titanium with mixed metal oxide) fixed to the hull and connected to a **DC power source**.
- The hull is connected to the **negative terminal**, anodes to the **positive terminal**.
- A controlled current flows from the anodes into seawater, making the **hull uniformly cathodic**.
- **Principle:** By **impressing a direct current**, the hull potential is maintained at a protective level (typically -0.85 V vs Ag/AgCl), preventing corrosion.

7. Explain EACH of the following terms:

- (a) galvanic corrosion; (2)
- (b) cavitation damage; (2)
- (c) erosion damage; (2)
- (d) stress corrosion; (2)
- (e) atmospheric corrosion. (2)

(a) Galvanic corrosion (2)

- Occurs when **two dissimilar metals** are electrically connected in an electrolyte (e.g., seawater).
 - The **more anodic metal** corrodes preferentially, protecting the cathodic metal.
-

(b) Cavitation damage (2)

- Caused by the **formation and collapse of vapour bubbles** in a liquid, typically near propellers or pump impellers.
 - The collapsing bubbles produce **shock waves and micro-jets**, leading to **pitting and surface erosion**.
-

(c) Erosion damage (2)

- Mechanical removal of material by the **impingement of solid particles or high-velocity fluids**.
 - Common in **pipe bends, valves, and pump casings** where turbulence is high.
-

(d) Stress corrosion (2)

- The **combined effect of tensile stress and a corrosive environment** causes cracking.
 - Occurs even at stress levels below the material's yield strength (e.g., in stainless steel exposed to chlorides).
-

(e) Atmospheric corrosion (2)

- Corrosion due to exposure to **moisture, oxygen, and pollutants** in the air.
- Common in **deck structures, superstructures, and above-waterline hull plating**.

8. (a) Describe with the aid of a sketch, how Bi-metallic strips are utilised to measure temperature. (8)
- (b) State a typical application for this type of device and its main shortcoming. (2)

(a) How bimetallic strips are used to measure temperature (8 marks)

- A **bimetallic strip** is made by bonding together **two dissimilar metals** with different coefficients of thermal expansion (e.g., brass and steel).
- When the strip is heated, one metal expands **more than the other**, causing the strip to **bend or curve**.
- The amount of curvature is **proportional to the temperature change**.
- This deflection can be used to:
 - Move a **pointer across a calibrated scale** (for temperature indication).
 - Make or break **electrical contacts** (for alarms, thermostats, or control circuits).
- **Sketch description** (if drawing in exam):
 - Show a bonded strip fixed at one end, free to bend at the other.
 - Arrow indicating deflection with temperature rise.
 - Pointer linkage to scale for temperature reading.

(b) Typical application and shortcoming (2 marks)

- **Application:**
 - Thermometers, thermostats (refrigeration plants, HVAC), engine room thermometers, simple temperature alarms.
- **Shortcoming:**
 - Relatively **slow response** due to thermal mass.
 - Limited **accuracy and sensitivity** compared with electronic devices.
 - Subject to **mechanical fatigue** after long-term use.

9. With reference to engine governors, explain EACH of the following terms:

- (a) sensitivity; (2)
- (b) hunting; (2)
- (c) speed droop; (2)
- (d) stability; (2)
- (e) isochronous governing. (2)

(a) Sensitivity (2)

- The ability of a governor to **detect and respond to small changes in engine speed**.
 - A highly sensitive governor will make fine corrections with minimal speed variation.
-

(b) Hunting (2)

- Continuous, **oscillatory variation of engine speed** around the set point due to over-correction by the governor.
 - Indicates poor damping or excessive sensitivity.
-

(c) Speed droop (2)

- The **percentage reduction in engine speed** between **no load and full load** at a fixed governor setting.
 - Introduced intentionally to allow **stable load sharing** between parallel-running engines.
-

(d) Stability (2)

- The ability of a governor to **maintain a steady speed** at a given load without oscillations or hunting.
 - Achieved through correct balance of sensitivity and damping.
-

(e) Isochronous governing (2)

- A condition where the governor maintains the **same speed at all loads (zero droop)**.
- No steady-state error, but can lead to **instability when load sharing** between multiple engines.

10. (a) State the reasons for fitting a pneumatic process valve with EACH of the following:
- (i) a volume booster; (2)
 - (ii) a feedback positioner. (2)
- (b) State, with reasons, the type of actuator fitted to the process valves for EACH of the following systems:
- (i) a fuel supply system in which the valve must not move on loss of power to the control system; *fail set* (3)
 - (ii) a lubrication oil cooling system in which the valve diverts the oil through a cooler. *fail safe.* (3)

(a) Reasons for fitting auxiliaries to pneumatic process valves

(i) Volume booster (2)

- Ensures **rapid response and movement** of large actuators by increasing the rate of air flow.
- Needed when the actuator volume is large and normal instrument air flow would be too slow.

(ii) Feedback positioner (2)

- Provides **accurate positioning of the valve** by feeding back stem position to the controller.
- Overcomes problems of **friction, hysteresis, and varying air supply pressure**, ensuring the valve reaches the demanded position.

(b) Type of actuator for specific systems

(i) Fuel supply system (valve must not move on loss of control power) (3)

- Use a **double-acting actuator with fail-in-place (fail-set) positioner**.
- Ensures valve **remains in last commanded position** if signal/power is lost → avoids unplanned fuel cut-off or flooding of fuel.

(ii) Lubricating oil cooling system (valve diverts oil through cooler, must be fail-safe) (3)

- Use a **spring-return actuator** designed to fail in the **safe position** (valve diverts oil through cooler) if power/control air is lost.
- Protects bearings and machinery by ensuring continued cooling → prevents overheating and damage.